

LO51-T02-T₀ Ladut Track-51]

Schedule XLV-Form No.134

R. W. D Benipatti DIVISION

R. W. D Benipatti SUB-DIVISION

MBN-1648

Measurement Book

Ba Jaiā Chāzā(11)

Table

1

Name of work—
 Situation of work—
 Agency by which work is executed—
 Date of measurement—
 No. and date of agreement.

(These four lines should be repeated at the commencement of the measurements relating to each work.)

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
(1) setting out of Pillars					
		2 Nos			
NW —		Lost — To 270			
		Lad out (Tape 5)			
Agcy: —		Beribhar Const			
57 m		57 m			
57 m		57 m			
Worked					
(1) setting out of Pillars					
		2 Nos			
(2) setting out of Pillars					
		10 Nos			
(3) Clearing and grading					
		2 x 30 x 3 = 180			
		5 x 20 x 3 = 300			
		6 x 20 x 3 = 360			
		9 x 20 x 3 = 540			
		10 x 30 x 3 = 900			

Continuation

