

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	

2ml Yearly maintenance

Name of work:- Langari Pakayto

Ambasia to Mamsy Road

Agency:- Subhash Ratan

Agreement:- 12 SBT / 2021-22

Complete date:- 30-8-22

A-Complete date:- 17-5-23

Record Entry

① Restoration of eavest/ beams with
moorum do-do-all

$$\Rightarrow 2 \times 69 \times 1.0 \times 0.3 = 41.4 \text{ m}^3$$

② making up of beams/ shoulder
do-do-all

$$\Rightarrow 2 \times 52 \times 2.25 = 234 \text{ m}^3$$

③ Patching repair over pot holes
bituminous surface with 20mm

$$\Rightarrow 1 \times 3.6 \times 2.25 = 8.1 \text{ m}^2$$

$$\Rightarrow 1 \times 2.8 \times 2.25 = 6.3 \text{ m}^2$$

$$\Rightarrow 1 \times 2.1 \times 2.25 = 4.7 \text{ m}^2$$

$$\Rightarrow 1 \times 3.2 \times 2.25 = 7.2 \text{ m}^2$$

$$\Rightarrow 1 \times 2.8 \times 2.25 = 6.3 \text{ m}^2$$

$$\text{Total} = 32.6 \text{ m}^2$$

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
⑤ maintenance of already planted trees for additional do-do all					
⇒ Qty 68 @ Rs 638					
					⇒ 42656/-00
					⇒ RS 46784 = 00
					Total = 85940 / = 00
					Total RS 85940 / = 00
Sivati kumari					S. Kumar
15/05/25					29.07.25
J.E					At

Material Statement

Soil - 234 m³

Bituminous - 0.124 MT

Emulsion -	17.9	0.018 MT
------------	------	----------

~~Stone chips - 1.7604 m³~~

Swati Kymari
15/05/25
J.E