

Tamkumbha
MES H. KUMAR
M.M.G. S.Y. अप्र 2015 (SC)
श 1048
Shedule XLV Form No. 134.

F.F. R.W.D(W)

DIVISION
F.F. R.W.D

A.F. R.W.D(W)

SUB-DIVISION
Tamkumbha

Measurement Book

MB No - 3022

C

2nd year maintenance Bill

67

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of work -					Construction of
Road from					Salethadih to L048
with					5th year maintenance
under					Head mmsy (se)
Agency -					Umesh Kumar
Vill + p.o -					Uteliyars, Asurain
					Tankupp
Pist -					Chay
Agg. No -					81/mmsy/se/SBP/
					2020-2021
Date of Commencement -					31/12/2020
Date of Completion -					21/12/2021
Date of Actual Completion -					

① Restoration of rain cuts/					
Berms with soil - mmsy					
etc do at job comp					
Qty -					
6x	30.0x0.60x0.30	2			32.40 m ³
4x	25.0x0.75x0.30	2			22.50 m ³
5x	15.0x0.50x0.30	2			11.25 m ³
4x	20.0x0.60x0.25	2			12.00 m ³
Total =					78.15 m ³
② making up of Berms/					
Shoulders, stripping excess					
soil from shoulders do at					
job comp.					
Qty -					

ABSTRACT OF COST

2nd year maintenance Bill

Sch. XIV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
① restoration of rain curbs					
Berm do —					
98.15 m ² by TMS page - (62)					
Q & 904.86/m ² = Rs 31577.24					
② mending of Berms/shoulder					
do —					
441.75 m ² by TMS page - (62)					
Q & 60.28/m ² = Rs 26629.24					
③ patch repair over pot holes with 20 mm pea mix					
do do — do —					
61.53 m ² by TMS page - (68)					
Q & 231.03/m ² = Rs 14215.24					
④ patch repair over bituminous surface with 20 mm mix					
seal surface — do —					
61.55 m ² by TMS page - (68)					
Q & 247.15/m ² = Rs 15207.24					
⑤ crack sealing and filling of cracks and joints					
do do do do —					
1320 mtr by TMS page - (63)					
Q & 3.71/mtr = Rs 4897.24					
Total Rs 92528.24					

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
⑥ Repair of isolated areas of damaged concrete					
per sq ft - do - do					
16.85 m ² by TMB page - (63)					
Q.R. 23/03/72 = R.					3888 24
⑦ Repair of old concrete					
do all - do - do					
339 m ² by TMB page - (63)					
Q.R. 24/13/72 = R.					8180 24
⑧ maintenance of ep works					
(HPC) do - do					
4 x 10 by TMB page - (63)					
Q.R. 1166.58 / No = R.					4666 24
⑨ maintenance of ep works					
(slab current) do - do					
2 x 10 by TMB page - (63)					
Q.R. 2394.56 / No = R.					4790 24
⑩ maintenance of Road Signposts					
do all - do - do					
1.68 km by TMB page - (70)					
Q.R. 1104.53 / km = R.					1856 24
					= R. 115505 24

B/E-11 11590521

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
(11) maintenance of 200 mtr					
9th km stone	do	do	do	do	
1.68 km by TMB page				$\frac{70}{11}$	
Q & 643.17/m			2 R		1081 21
(12) Cutting of branches of trees and shrubs					
do - do					
10 No by TMB page				$\frac{70}{12}$	
Q & 113.64/m			2 R		1136 21
(13) Cutting of shrubs from Roadway					
do - do					
1320 No by TMB page				$\frac{70}{13}$	
Q & 6.38/m			2 R		9214 21
(14) Trimming of grass and weeds					
2970 m ² by TMB page				$\frac{70}{14}$	
Q & 2.33/m ²			2 R		6920 21
(15) White washing of parapet walls of ch naka and face of concrete slab culverts					
do - do					
104.80 m ² by TMB page				$\frac{70}{15}$	
Q & 16.80/m ²			2 R		1761 21

[illegible]