

At. No - 1189 dt 30.03.25
length - 56.64m

Major Construction Cost.	536.174 lacs
Minor Improvement	
Initial Rectification	
5th Year Periodic Renewal	
Total Maintenance Cost	2.713 lacs
(1st, 2nd, 3rd, 4th, 6th & 7th):	
Other Cost:	
Emergent Cost	
Contingency Cost	3.180 lacs
Administrative Cost	12.063 lacs
Total	₹ 554.139 lacs

TIS Details

Major Construction Cost.	516.396 lacs
Minor Improvement	
Initial Rectification	
5th Year Periodic Renewal	
Total Maintenance Cost	3.235 lacs
(1st, 2nd, 3rd, 4th, 6th & 7th):	
Other Cost:	
Emergent Cost	
Contingency Cost	
Administrative Cost	
Total	₹ 519.631 lacs

T.S. No. dt.
Ref. S.E. Letter No. dt.
Technical Sanction Accorded for Rs. 519.631 lacs
(Rupees five crore nineteen lacs sixty
three thousand one hundred only)

Technical Sanction does not mean sanction of rate. Instruction given in technical note should be followed strictly.

A.E. h E.E. nd Tech. Secy dt

Original Copy

1412
CE-21
24/4/2025