

Name of Road! - Sidhuliya And Sadak To
Buddho Rai ke Talay

(Under MIMSY S.C.)

Schedule XLV-Form No. 134

Name of Agency! - M/S Binod Kumar Upadhyay
DIVISION

Block! Sidhuliya

SUB-DIVISION

M.B.No-516

MEASUREMENT BOOK

Abstract of Cost:

38

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
① Repairing of Rain cask/Beam					
12.29 m ² VTMB Page No. (36)					
@ Rs. 379.59 =					4665
② Making of house/shoulder					
433.79 m ² VTMB Page No. (36)					
@ Rs. 57.01 =					24730
③ Repair of pot holes with 75mm					
14.01 m ² VTMB Page No. (37)					
@ Rs. 460.14 =					6442
④ Repair of pot with seal coat					
14.01 m ² VTMB Page No. (37)					
@ Rs. 284.73 =					3989
⑤ Maintenance of Road sign					
0.63 km VTMB Page No. (37)					
@ Rs. 1054.28 =					664
⑥ Maintenance of 20mm and 10mm stone					
1.26 km VTMB Page No. (37)					
@ Rs. 688.7 =					867
⑦ Cutting of branches of tree on					
1 No. VTMB Page No. (37)					
@ Rs. 106.2 =					106
⑧ Cutting of shrubs from road					
2 No. VTMB Page No. (37)					
@ Rs. 6.51 =					13
⑨ Trimming of grass and weeds					
198.9 m ² VTMB Page No. (37)					
@ Rs. 2.17 =					432

Continuation

Continuation