

Harriet Vork: - Ladu Badheya Path me Bsham Ping
TB Dem Tal Hotelhu Badu Tal

Schedule XLV-Form No. 134

Quas - Ortel (NDS) Birics

DIVISION

Name of Agency: M/S Ravi Const.

SUB-DIVISION

RWD-2 GCP M.B.No-431

Measurement Book

4

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Abstract of cost					
① Restoration of Rain Cuts / borms					
Qty vide item No ① & Page No. (41) of MB					
i.e 130.19 m ³					
② making up borms / shoulder					
Qty vide item No ② & Page No. (41) of MB					
i.e 622.33 m ³					
③ Repair of pot holes filled with 75 mm Bm					
Qty vide item No ③ & Page No. (42) of MB					
i.e - 7.78 m ³					
④ Patch repair over pot holes with 20 mm Premix Carpet					
Qty vide item No ④ & Page No. (42) of MB					
i.e - 129.40 m ²					
⑤ Patch repair over bituminous Surface with 20mm Premix Carpet					
Qty vide item No ⑤ & Page No. (42) of MB					
i.e - 129.40 m ²					
⑥ Providing and laying of hot applied Thermoplastic compound for B.T					

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
(13) Trimming of grass and weeds from shoulder.					
Qty. vide item no. (13) & page no. (43) of Imp. Ge.					931.65 m ²
(a) 2.2 / m ²				2	2050.00
(14) white washing of parapet wall of CD work and free truck.					
Qty. vide item no. (14) & page no. (43) of Imp. Ge.					73.04 m ²
(a) 16.16 / m ²				2	1180.00
				2	579119.00
Below @ 10% APA				2	57912.00
Net Amt.				2	521207.00

28/10/24
 S.E.
 28.10.24
 S.E.

Material statement -

$$E/W = 190.99 \text{ m}^3$$

$$RSI = 0.1036 \text{ m}$$

$$SSI = 0.093 \text{ m}$$

$$SQO = 1.09 \text{ m}$$

$$\text{Stone chips} = 16.347 \text{ m}^3$$

28/10/24
 S.E.

Continuation