

Schedule XLV-Form No. 134

DIVISION

SUB-DIVISION

MEASUREMENT BOOK

M.B.No. 3135

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
N/w:- maintenance of road from Tol to Pipra Se Bhardwaj					
Tola Se Ahir Tola.					
Agency:- Rabintra W. Singh					
Agg. no:- 51550/2019-20					
D. O. A.C :- 26.03.2020					

① Restoration of raincuts

Berm with Soil

14 X 2.00 m X 0.70 m X 0.30 m	= 5.88 m ³
10 X 2.50 m X 0.70 m X 0.30 m	= 5.25 m ³
17 X 3.00 m X 0.70 m X 0.30 m	= 10.71 m ³
3 X 15.00 m X 0.70 m X 0.30 m	= 9.45 m ³
2 X 14.60 m X 0.70 m X 0.30 m	= 6.13 m ³
7 X 8.00 m X 0.70 m X 0.30 m	= 11.76 m ³
5 X 12.00 m X 0.70 m X 0.30 m	= 12.60 m ³
X 25.00 m X 0.70 m X 0.30 m	= 10.50 m ³
2 X 9.50 m X 0.70 m X 0.30 m	= 4.00 m ³
4 X 4.70 m X 0.70 m X 0.30 m	= 2.95 m ³
	80.23 m ³

② making up of berms

Shoulder stripping

2 X 2 X 30.00 m X (0.70 + 0.60) m	= 90.00 m ³
15 X 2.00 m X 0.70 m	= 21.00 m ³
32 X 3.00 m X 0.70 m	= 67.20 m ³
10 X 5.00 m X 0.70 m	= 35.00 m ³
8 X 8.00 m X (0.70 + 0.80) m	= 48.00 m ³

Continuation

C/o 261.20 m³

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
4x 25.00m x 0.70m =					70.00m ²
2x 18.00m x 0.70m =					25.20m ²
5x 7.00m x 0.70m =					24.50m ²
5x 4.00m x 0.70m =					14.00m ²
2x 3.50m x 0.70m =					4.90m ²
					399.60m ²
③ Repair of pot holes filled with 75mm —					
6x 1.50m x 1.70m =					15.30m ²
2x 1.80m x 1.50m =					5.40m ²
2x 2.00m x 1.60m =					6.40m ²
4x 2.25m x 1.75m =					15.75m ²
2x 3.00m x 1.80m =					10.80m ²
2x 3.50m x 2.25m =					15.75m ²
1x 5.00m x 2.20m =					11.00m ²
1x 4.10m x 1.10m =					4.51m ²
					93.51m ²
④ Repair over pot holes —					
Qty. Same as					
1. no :- ③ = 93.51m ²					
⑤ Repair over bituminous Surface —					
Qty. Same as 1. no :- ③					
= 93.51m ²					
⑥ main ⁿ of H.P. Culvert					
= 2 nos					

Continuation

Continuation

ABSTRACT of COST

74

Sch. XLV—Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
① Restoration of raincuts/ Berms with Soil ———— Qty. wide Tmsl (71) 1 no :- (1) = 80.23 m² @ Rs 365 = 29/m² Mr 29304=∞					
② making up of berms/ Shoulder ———— Qty. wide Tmsl (72) 1 no :- (2) = 399.80 m² @ Rs 54 = 16/m² Mr 21653=∞					
③ Repair of pot holes filled with 75mm — Qty wide Tmsl (72) 1 no :- (3) = 93.51 m² @ Rs 362 = 43/m² Mr 3891=∞					
④ Repair of pot holes with 20mm — Qty. wide Tmsl (72) 1 no :- (4) = 93.51 m² @ Rs 304 = 26/m² Mr 28451=∞					
⑤ Repair over bitumi- nous surface — Qty. wide Tmsl (72) 1 no :- (5) = 93.51 m² @ Rs 323 = 84/m² Mr 20282=∞					
⑥ maint ⁿ of H.P. Culvert ———— C/c Mr 142581=∞					

Continuation

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Qty. vide TMBP (72)					
1. no :- (6) = 2 nos.					
@ M-113 = 64/no. M-2263=∞					
(7) maint ⁿ of road sign —					
Qty. vide TMBP (73)					
1. no :- (7) = 0.14 Km					
@ M-1087 = 62/Km M-152=∞					
(8) maint ⁿ of 200m and					
Km Stone					
Qty. vide TMBP (73)					
1. no :- (8) = 0.22 Km					
@ M-654 = 33/Km M-149=∞					
(9) Cutting of Shrubs					
From roadway					
Qty. vide TMBP (73)					
1. no :- (9) = 8 nos.					
@ M-6 = 60/no. M-53=∞					
(10) Cutting of branches					
of trees and shrubs —					
Qty. vide TMBP (73)					
1. no :- (10) = 2 nos.					
@ M-107 = 48/no. M-215=∞					
(11) P/L of hot applied					
thermoplastic —					
Qty. vide TMBP (73)					
1. no :- (11) = 180.00m					
@ M-942 = 89/m M-69720=∞					
C/o M-316128=∞					

Continuation

