## कार्यपालक अभियंता का कार्यालय ग्रामीण कार्य विभाग, कार्य प्रमंडल, चकिया, (पूर्वी चम्पारण),

पत्रांक: 12.65 अनु0 / चिकया, दिनांक: 13 / 08 / 2020

प्रेषक

कार्यपालक अभियंता ग्रामीण कार्य विभाग कार्य प्रमंडल, चकिया।

सेवा मे

अपर मुख्य कार्यपालक पदाधिकारी—सह—सचिव बिहार ग्रामीण पथ विकास एजेंसी, ग्रामीण कार्य विभाग, बिहार, पटना।

विषय— एम०एम०जी०एस०वाई० (जेनरल) योजना के अन्तर्गत निर्माणाधीन पथ के लिए निधि उपलब्ध कराने के संबंध में।

महाशय,

उपर्युक्त विषय के संबंध में कहना है कि एम०एम०जी०एस०वाई० (ज़ेनरल) योजना अन्तर्गत निर्माणाधीन पथ का पथवार मांगी जाने वाली आवंटन की सूचीं पत्र के साथ भवदीय के अवलोकनार्थ एवं आवश्यक कार्रवाई हेतु समर्पित की जा रही है।

अतः संलग्न सूचि के अनुसार आवंटन उपलब्ध कराने की कृपा की जाय।

अनु0:- 1. आवंटन की सूची

2. मापीपुस्त की छाया प्रति।

विश्वासभाजन,

कार्यपालक अभियन्ता ग्रामीण कार्य विभाग कार्य प्रमण्डल—चकिया

Scanned by CamScanner

## Rural Works Department MMGSY (Gen) Allotment Requisition Format

SI. Year Volume of Road Volume of Road Bricks In Language Bricks In Language In	_	Vame of	Name of Division :- Chakia									1	
2 3 4 5 6 7 8 9 9 10 In English (In English) (In KM) (In Lacs) (In	L	41.	y e	Name of	Admí	nistrative nction	Agree	ement (In Lacs)	Allotment	Total Expenditure as	Value of	Current Demand	odramad
Sundarapur Mauje Tola Near Chilar Pathak House to Bricks         4         5         6         7         8         9         10         11         12           Chilar Pathak House to Bricks Near Jalu Rai House         Adarsh Kumar         1.239         98.67000         87.63672         8.96795         20.28731         19.75456         34.48570         14.19839           Total         1.239         98.67000         87.63672         8.96795         20.28731         19.75456         34.48570         14.19839	2	100		(In English)	Length (In KM)	Amount (In Lacs)	Main Work	Mantenance	Received (In Lacs)	per MIS (In Lacs)	(In Lacs)	(in Lacs) (11-9)	
Sundarapur Mauje Tola Near         Adarsh Kumar         1.239         98.67000         87.63672         8.96795         20.28731         19.75456         34.48570         14.19839           Near Jalu Rai House         Total         1.239         98.67000         87.63672         8.96795         20.28731         19.75456         34.48570         14.19839		1 2	E	4	5	9	7	8	6	10	11	12	13
1.239 98.67000 87.63672 8.96795 20.28731 19.75456 34.48570		1 2018-1	- J= -	Adarsh Kumar	1.239	98.67000	87.63672	8.96795	20.28731	19.75456	34 48570	14.19839	work in Progress
	1. 1		Total		1.239	98.67000	87.63672	1	20.28731	19.75456	34.48570	14.19839	

1. खर्च का मिलान MIS से हो गया है।

2. अधियाचित राशि का पथवार मापीपुस्त की प्रथम एवं अंतिम पेज की अभिप्रमाणित छाया प्रति संलग्न की जा रही है

3. पूर्व निर्मत राशि का उपयोगिता प्रमाण पत्र संलग्न की जा रही हैं।

. योजनावार सभी पथों का अधियाचना एक साथ भेजी जा रही है।

5 निर्गत साश्री का डी0 सी0 विपत्र 15 दिन के अन्दर ब्राज्ञा कार्यालय में उपलब्ध कराया जाना आवश्यक है।

Executive Engineer Rural Works Division, Chakia

RURAL WORKS DEPARTMENT WORKS DIVISION- CHAKIAYA.

13.08,20

## Form GER 19-A (See Government of India's decision (1) bellow Rule - 150) Form of utilization certificate up to the month up to 08/2020 MMGSY (GEN) 'CFMS'

PIU - RWD, W.D- CHAKIA

SL.	Nume of Schame	Sanction No. / Date with Amount (in RS. Lachs)	Amount Received (in RS. Lacks)	particulars
	MMGSY (GEN) 'CFMS'	742.00441	742.00441	Certified that out of Rs.74200441 Lacks riceive upto the year.2019-20 executive engineer R W D (W) DIV, chakia a sum of RS.730.27695 Lacks has been utilized for the perpose of MMGSY (GEN) 'CFMS' Schemes given in the margin for which it was sanctioned and the balance of Rs. 11.72746 lacks remaining unutilized at this end of the (up to 08/2020)
	410.		V.	

- 2. Certificate that I have satisfied myself that the conditions on which the grand's-in-aid was sanctioned have been duly fulfilled/ate being fulfilled and that have exercised the following checks to see that the money was actually utilized for the purpose for which it was sanctioned kinds of cheks exercised:
  - a. Works have been supervised by Executive Engineer/ Superintending Engineer.
  - b. Periodical inspection has been conducted by Executive Engineer/ Superintending Engineer.
  - c. Construction materials have been tested.
  - d. Measurements have been recorded in the MBs and test check conducted by the Assistant.
- 3. Physical Progress achieved :
  - e. Construction of MMGSY (Details in Progress report)

  - g. GSB entered in MB has been hadly damage due to flood in Dekha Bandh to Ajit Singh ke Tola Tak Path

RURAL WORKS DEPARTMENT WORKS DIVISION- CHAKIAYA.

EXECUTIVE ENGINEER,
RURAL WORKS DEPARTMENT
WORKS DIVISION- CHAKIA.