

FIELD INSPECTION REPORT

Date of Inspection : 02/12/2020		District: East Champaran, Motihari	
Division : Works Division, Motihari		Length (km): 3.400	
Name of the Road: Motihari circuit Houle ke bagal se maganohar Hardiya Motihari			
Scheme/Programme:		MAINTENANCE (New maintenance Policy 2018)	
Package No.:		Road Id No.:	
Status of the Project:		Ongoing/Completed/Under Maintenance	
Work is a case of:		New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No N/A -
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Gross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	- N/A -

Overall Rating :

Satisfactory (S)	-	"S"
Satisfactory but requires Improvement (SRI)	-	-
Unsatisfactory (U)	-	-

NAME: SANTAY KUMAR
 Executive Engineer
 DESIGNATION: R.W.D. (W) Division
 Motihari


 (Signature)
 2/12/20
 JK