

FIELD INSPECTION REPORT

Date of Inspection : 02/11/2020	District: SAHARSA
Division : SIMRI BAKHTIYARPUR	Length (km): 2.50
Name of the Road: BAHURWA KOSI BANDH TO GORIYARI	
Scheme/Programme: MAINTENANCE	M-R 2018
Package No.:	Road Id No.:
Status of the Project: Ongoing/Completed/Under Maintenance	
Work is a case of: New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	SAT N-A
b)	Condition of Surfacing	SAT N-A
c)	Riding Quality	SAT N-A
d)	Road Camber	SAT N-A
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No N-A
f)	Contraction Joints provided or not (CC Pavement)	Yes/No N-A
g)	Compaction of flank/slope & raincuts if any	Yes/No N-A
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U N-A
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U S
c)	Condition of railings/slab/approach for Bridges	S/SRI/U N-A
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No Citizen informatory Board. Only.
4.	Compliance History	
a)	Status of ATR's & any others	NO

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

WORK NOT STARTED

AR
02/11/20

(Signature)

NAME: AMIT KUMAR
JE

Executive Engineer,
R.W.D. Works Division,
Simri Bakhtiyarpur