## FIELD INSPECTION REPORT

Date ofo Inspection: 02 12 2020			District : GAYA	
Divison : Neemchak Bathani			Length (Km.: 0.547	
Scheme/Programme: MAINTENANCE - 18				
Package No.	Repair & main	Typhomila Arit	Road Id No. :	
Status of the Project : Ongoing/Completed/Under-Maintenance				
Work is a case of	of:	New Connectivity/Up	gradation/Maintenance	
SI.		Parameters to be check	ed	Remarks
No.  1 Pavement				land
a) Road Junction condition				S/K
Condition of Surfacing				SX
) Riding Quality				S/P
) Road Camber				SAC MER/No
	way the feet from defects such as visible cracks, exposed aggregates in case of CC Pavement.			
The state of the s				
the of Coult clane & rainouts if any ( Nee to but land flank what is				Veren Ves/blo
2 Cross Drai				S/ <del>ORI</del> /L/
Condition of head walls in Hume pipe culverts including its painting				SASRIAL
Condition of Abutment & Wing walls, Slab in RCC culverts				
	f railings/slab/approach		NA	S/SRI/U
			20	ed and
Whether sign	n boards/informatory/ca	utionary Board/km & 200m ston	es/Pavement road markings are provide	Yes/No
Compliance History				NIL
Status of AT	R's & any others.			
erall Rating				9
Cian Aming	Satisfactory (S)			
	Satisfactory but requi	res Improvement (SRI)		
	Unsatisfactory (U)			
			一多过少?	Nimchar