## FIELD INSPECTION REPORT

District: Palng		
Length (km): 2.56 KM		
i hoad to Akona		
NCE A! New 2018		
Road Id No.:		
Ongoing/Completed/Under Maintenance		
ivity/Up gradation/ Maintenance		
1		

Sl. No.	Parameters to be checked	Remarks
1.	Payement	
a)	Road Junction condition	√\$/U
b)	Condition of Surfacing	~∕s/U
c)	Riding Quality	√s/U
d)	Road Camber	~∕s/u
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
	Grove Dinathinge	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
ъ)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
	Roni Familiane	nt.
a 1	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	VYes/No
	Compilance Almory	
a) :	Status of ATR's & any others	NO

Overall Rating

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	2

(Signature)

NAME: Ajay Kumar lingh DESIGNATION: Executive Engineer NH