

# FIELD INSPECTION REPORT

DATE OF INSPECTION:	02/12/2020	DISTRICT:	PURNEA
DIVISION:	DHAMARHA	LENGTH:	5.350 KM
NAME OF THE ROAD:	BARKONGA to Dalkita		
SCHEME/PROGRAMME:		MAINTENANCE	(MR-3054-HE 40)
PACKAGE No:		ROAD ID No.:	21105202047
STATUS OF THE PROJECT:	ONGOING/COMPLETED/UNDER MAINTENANCE		
WORK IS A CASE OF:	NEW CONNECTIVITY/UP GRADATION/MAINTENANCE		
SL NO	PARAMETERS TO BE CHECKED	REMARKS	
1	PAVEMENT		
A	ROAD JUNCTION CONDITION	S	
B	CONDITION FO SURFACING	S	
C	RIDING QUALITY	S	
D	ROAD CAMBER	S	
E	WHETHER FREE FROM DEFECTS SUCH AS VISIBLE CRACKS, EXPOSED AGGREGATES IN CASE FO CC PAVEMENT	YES	
F	CONTRACTION JOINTS PROVIDED OR NOT(CC PAVEMENT)	N/A	
G	COMPACTION OF FLANK/SLOPE & RAINCUTS IF ANY	YES	
2	CROSS DRAINAGE		
A	CONDITION OF HEAD WALLS IN HUME PIPE CULVERTS INCLUDING ITS PAINTING	S	
B	CONDITION OF ABUTMENT & WING WALLS, SLAB IN RCC CULVERTS	S	
C	CONDITION OF RAILINGS/SLAB /APPROACH FOR BRIDGES	S	
3	ROAD FURNITURE		
A	WHETHER SIGN BOARDS /INFORMATORY BOARD/ KM & 200 M STONES/PAVEMENT ROAD NARKING ARE PROVIDED AND MAINTAINED	YES	
4	COMPLIANCE HISTORY		
A	STATUS OF ATR's & ANY OTHERS	No Any ATR	
OVERALL RATING			
	SATISFACTORY(S)	S	
	SATISFACTORY BUT REQUIRES IMPROVEMENT(SRI)	-	
	UNSATISFACTORY(U)	-	

NAME: Arjun Kumar Singh  
DESIGNATION: E-E ROAD C.O.D. Dhamdaha

02.12.20  
SIGNATURE  
E-E ROAD C.O.D. Dhamdaha