

# FIELD INSPECTION REPORT

DATE OF INSPECTION:	02/12/2020		DISTRICT:	PURNEA
DIVISION:	DHAMDHAHA		LENGTH:	1.50 km
NAME OF THE ROAD:	Mahabir Stn on mirgan falka (SH77) to Kanyara Stn.			
SCHEME/PROGRAMME:	MAINTENANCE MR(3054)-H&D			
PACKAGE No:	ROAD ID No.: 2.1105202195			
STATUS OF THE PROJECT:	ONGOING/COMPLETED/UNDER MAINTENANCE			
WORK IS A CASE OF:	NEW CONNECTIVITY/UP GRADATION/MAINTENANCE			
SL.NO	PARAMETERS TO BE CHECKED		REMARKS	
1	PAVEMENT			
A	ROAD JUNCTION CONDITION		S	
B	CONDITION FO SURFACING		S	
C	RIDING QUALITY		S	
D	ROAD CAMBER		S	
E	WHETHER FREE FROM DEFECTS SUCH AS VISIBLE CRACKS, EXPOSED AGGREGATES IN CASE FO CC PAVEMENT		Yes	
F	CONTRACTION JOINTS PROVIDED OR NOT(CC PAVEMENT)		H/A	
G	COMPACTION OF FLANK/SLOPE & RAINCUTS IF ANY		Yes	
2	CROSS DRAINAGE			
A	CONDITION OF HEAD WALLS IN HUME PIPE CULVERTS INCLUDING ITS PAINTING		S	
B	CONDITION OF ABUTMENT & WING WALLS, SLAB IN RCC CULVERTS		S	
C	CONDITION OF RAILINGS/SLAB /APPROACH FOR BRIDGES		S	
3	ROAD FURNITURE			
A	WHETHER SIGN BOARDS /INFORMATORY BOARD/ KM & 200 M STONES/PAVEMENT ROAD NARKING ARE PROVIDED AND MAINTAINED		Yes	
4	COMPLIANCE HISTORY			
A	STATUS OF ATR's & ANY OTHERS		No Any ATR	
OVERALL RATING				
	SATISFACTORY(S)		S	
	SATISFACTORY BUT REQUIRES IMPROVEMENT(SRI)		—	
	UNSATISFACTORY(U)		—	

NAME: Arjun Kumar Singh  
DESIGNATION: GERD(W.D) Dhamdaha

02.12.20  
SIGNATURE  
GERD(W.D) Dhamdaha