

# FIELD INSPECTION REPORT

DATE OF INSPECTION:	02/12/2020	DISTRICT:	PURNEA						
DIVISION:	DHAMDHA	LENGTH:	4.240 km						
NAME OF THE ROAD:	Jamalpur chowk Rangpur to 4th								
SCHEME/PROGRAMME:	MAINTENANCE (MR-3054-NEW)								
PACKAGE No:	ROAD ID No.: 21105301001.								
STATUS OF THE PROJECT:	ONGOING/ <input checked="" type="checkbox"/> COMPLETED/UNDER MAINTENANCE								
WORK IS A CASE OF:	NEW CONNECTIVITY/ <input checked="" type="checkbox"/> UP GRADATION/MAINTENANCE								
SL.NO	PARAMETERS TO BE CHECKED	REMARKS							
1	PAVEMENT								
A	ROAD JUNCTION CONDITION	S							
B	CONDITION OF SURFACING	S							
C	RIDING QUALITY	S							
D	ROAD CAMBER	S							
E	WHETHER FREE FROM DEFECTS SUCH AS VISIBLE CRACKS, EXPOSED AGGREGATES IN CASE OF CC PAVEMENT	yes							
F	CONTRACTION JOINTS PROVIDED OR NOT(CC PAVEMENT)	NA							
G	COMPACTION OF FLANK/SLOPE & RAINCUTS IF ANY	yes							
2	CROSS DRAINAGE								
A	CONDITION OF HEAD WALLS IN HUME PIPE CULVERTS INCLUDING ITS PAINTING	NA							
B	CONDITION OF ABUTMENT & WING WALLS, SLAB IN RCC CULVERTS	NA							
C	CONDITION OF RAILINGS/SLAB /APPROACH FOR BRIDGES	NA							
3	ROAD FURNITURE								
A	WHETHER SIGN BOARDS /INFORMATORY BOARD/ KM & 200 M STONES/PAVEMENT ROAD MARKING ARE PROVIDED AND MAINTAINED	yes							
4	COMPLIANCE HISTORY								
A	STATUS OF ATR's & ANY OTHERS	No Any ATR							
OVERALL RATING	<table border="1"> <tr> <td>SATISFACTORY(S)</td> <td>S</td> </tr> <tr> <td>SATISFACTORY BUT REQUIRES IMPROVEMENT(SRI)</td> <td>-</td> </tr> <tr> <td>UNSATISFACTORY(U)</td> <td>-</td> </tr> </table>			SATISFACTORY(S)	S	SATISFACTORY BUT REQUIRES IMPROVEMENT(SRI)	-	UNSATISFACTORY(U)	-
SATISFACTORY(S)	S								
SATISFACTORY BUT REQUIRES IMPROVEMENT(SRI)	-								
UNSATISFACTORY(U)	-								

NAME: Arjun Kumar Singh

DESIGNATION: Executive Engineer  
Road Works Department  
District Engineer, Dhamdha, Purnea

Signed  
02.12.20  
SIGNATURE: Engineer  
Road Works Department  
District Engineer, Dhamdha, Purnea