

FIELD INSPECTION REPORT

Date of Inspection : 02-12-2020		District: Katihar
Division : BARSOI		Length (km): 19.5 KM
Name of the Road: Bijuria NH-31 Bijaragon to Adampur via Dhapi Tetra Madhoper		
Scheme/Programme: MAINTENANCE (OLD)		
Package No.: -		Road Id No.: -
Status of the Project: Ongoing/Completed/Under Maintenance		
Work is a case of: New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	√S/U
b)	Condition of Surfacing	√S/U
c)	Riding Quality	√S/U
d)	Road Camber	√S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	√Yes/No
f)	Contraction Joints provided or not (CC Pavement)	√Yes/No
g)	Compaction of flank/slope & raincuts if any	√Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	√S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	√S/SRI/U
c)	Condition of railings/slab/approach for Bridges	√S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	√Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	- N/A -

Overall Rating :

Satisfactory (S)	"S"
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

(Signature) AE (Biharampur)
02/12/2020

NAME: VIKAS KUMAR

DESIGNATION: ASSISTANT ENGINEER