

FIELD INSPECTION REPORT

Date of Inspection : 02.12.2020	District: Vaishali
Division : Hazibpur	Length (km): 3.50
Name of the Road: Madhapur to Mohdi Nagar via Chakdaha	
Scheme/Programme: MAINTENANCE	3054 MR
Package No.:	Road Id No.:
Status of the Project:	Ongoing/Completed/Under Maintenance
Work is a case of:	New Connectivity/Upgradation/Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓ SU
b)	Condition of Surfacing	✓ SU
c)	Riding Quality	✓ SU
d)	Road Camber	✓ SU
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	NA
f)	Contraction Joints provided or not (CC Pavement)	NA
g)	Compaction of flank/slope & raincuts if any	✓ Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	✓ SRIU
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	✓ SRIU
c)	Condition of railings/slab/approach for Bridges	✓ SRIU
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board km & 200m stones/Pavement road markings are provided and maintained	✓ Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	NA

Overall Rating :

Satisfactory (S)	✓
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NAME:

DESIGNATION:

Yay
2/12/20

E.E.
R.UD
work div.
Hazibpur

(Signature)