

FIELD INSPECTION REPORT

Date of Inspection: 02-12-2020 District: - Vaishali
 Division: - Hazipur Length (km): 4.810
 Name of the Road: Nandlalpur to Husainpur
 Scheme Programme: MAINTENANCE (New Maintenance Policy) 3654
 Package No.: Road Id No.: MR
 Status of the Project: Ongoing Completed Under Maintenance
 Work is a case of: New Connectivity Up gradation Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓ S
b)	Condition of Surfacing	✓ S
c)	Riding Quality	✓ S
d)	Road Camber	✓ S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No ✓
f)	Contraction Joints provided or not (CC Pavement)	NA
g)	Compaction of flank/slope & raincuts if any	NA
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	✓ SRIU
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	✓ SRIU
c)	Condition of railings/slab/approach for Bridges	✓ SRIU
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board km & 200m stones/Pavement road markings are provided and maintained	✓ Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S) ✓
 Satisfactory but requires Improvement (SRI)
 Unsatisfactory (U)

NAME:

DESIGNATION:

per
 2/12
 E.E
 R.W.D
 Hazipur

(Signature)