FIELD INSPECTION REPORT

Date of Inspection:	02.12.2020	District: SITAMARHI		
Division:	ELSAND	Length (km): 1·G7 KM,		
Name of the Road: SARKHAULI PIND ROAD TO SARKHAULI VILLAGE				
Scheme/Programme:	MAINTENANCE			
Package No.:		Road Id No.:		
Status of the Project:	Ongoing/Completed/Under Maintenance			
Work is a case of:	New Connectivity/Up gradation/ Maintenance			

Sl. N	Parameters to be checked	Remarks	
1.	Pavement		
• a)	Road Junction condition	-8/U	
b)	Condition of Surfacing	-8/U	
c)	Riding Quality	-8/Ú	
d)	Road Camber	-8/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No	
f)	Contraction Joints provided or not (CC Pavement)	Yes/No	
g)	Compaction of flank/slope & raincuts if any	Yes/No	
• 2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	-S∕SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	∽s/sri/u	
c)	Condition of railings/slab/approach for Bridges	∽S/SRI/U	
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No	
4.	Compliance History		
a)	Status of ATR's & any others	· NO	

Overall Rating :

Satisfactory (S)	115"
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

(Signature) 2 %

NAME: PARUEZ ALAM

DESIGNATION: E. E. BELSAND