

FIELD INSPECTION REPORT

Date of Inspection : 02/12/2020	District: ARAWAL
Division : ARAWAL	Length (km): 11.50 KM
Name of the Road: REPAIR OF ROAD FROM KRAPI BLOCK HEADQUARTER TO 12 th MILE (NH-110)	
Scheme/Programme: MAINTENANCE	
Package No.:	Road Id No.:
Status of the Project: Ongoing/Completed/Under Maintenance	
Work is a case of: New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓ S/U
b)	Condition of Surfacing	✓ S/U
c)	Riding Quality	✓ S/U
d)	Road Camber	✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	Yes/No / Partially
f)	Contraction Joints provided or not (CC Pavement)	✓ Yes/No
g)	Compaction of flank/slope & <u>cut</u> if any	✓ Yes/No
2.	Cross Drainage	
a)	Condition of head walls in <u>stone</u> pipe culverts including its painting	S SRI/U Partially
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S SRI/U N/A
c)	Condition of railings/slab/approach for Bridges	S SRI/U N/A
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓ Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	No-ATR

Overall Rating :

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

S

Am
02/12/2020
(Signature)

NAME: PRAVEEN KUMAR