

FIELD INSPECTION REPORT

Date of Inspection: 02/12/2020		District: Katihar
Name of Road:	Repair of road from T-02 Bastauli to Hundaili	
Scheme/ Programme:	MAINTENANCE (MR 3054)	
Package No.	Road ID No. 21105708026	
Status of the Project:	Completed	
Work is a case of:	Maintenance	
Sl.No	Parameters to be Checked	Remarks
1	Pavement	
a)	Road Junction Condition	S
b)	Condition of Surfacing	S
c)	Riding Quality	S
d)	Road Camber	S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	Yes
f)	Contraction Joints provided or not (CC Pavement)	Yes
g)	Compaction of flank/slope & raincuts if any	Yes
2	Cross Drainage	
a)	Condition of headwalls in Humepipe culverts including its painting	S
b)	Condition of Abutment & Wings walls, Slab in RCC culverts	S
c)	Condition of railings/slabs/approach for Bridges	S
3	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/Km & 200m stone/ Pavement road markings are provided and maintained.	Yes
4	Compliance History	
a)	Status of ATR & any others	Nil

Overall Grading:

Satisfactory (S)	(S)
Satisfactory but requires Improvement(SRI)	
Unsatisfactory (U)	

Name:
Designation

Satish Chaudhary
AE, Pranpur
RWD (W) Division Manihari

Satish Chaudhary
02/12/2020
(Signature)