

FIELD INSPECTION REPORT

Date of Inspection: 02/12/2020		District: Katihar	
Name of Road:		Repair of road from Maniya to Kuraitha	
Scheme/ Programme:		MAINTENANCE (MR 3054)	
Package No.		Road ID No. 21105708028	
Status of the Project:		Completed	
Work is a case of:		Maintenance	
Sl.No	Parameters to be Checked		Remarks
1	Pavement		
a)	Road Junction Condition	S	
b)	Condition of Surfacing	S	
c)	Riding Quality	S	
d)	Road Camber	S	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	Yes	
f)	Contraction Joints provided or not (CC Pavement)	Yes	
g)	Compaction of flank/slope & raincuts if any	Yes	
2	Cross Drainage		
a)	Condition of headwalls in Humepipe culverts including its painting	S	
b)	Condition of Abutment & Wings walls, Slab in RCC culverts	S	
c)	Condition of railings/slabs/approach for Bridges	S	
3	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/Km & 200m stone/ Pavement road markings are provided and maintained.	Yes	
4	Compliance History		
a)	Status of ATR & any others	Nil	

Overall Grading:

Satisfactory (S)	(S)
Satisfactory but requires Improvement(SRI)	
Unsatisfactory (U)	

Name:
Designation

Satish Chaudhary
AE, Pranpur
RWD (W) Division Manihari

Satish
02/12/2020
(Signature)