Date	of Inspection	THELD INSPECT	ION REPORT	
Divisi	of Inspection: 0	2.12.2020	District: Kistanganj'	
Name	of the Road:	any - 2	ength (km):	
Schen	ie/Programme:	epair of Road	from Taiyabour to	Dalua H.
Packa	ge No.:	MAINTENANCE		
Status	of the Project:	Ongoing/Completed/Un	ond Id No.: 212059080	50
Work	is a case of:	New Connectivity/Up g		
Sl. No	and the state of the state of	Parameters to be		Remarks
1.	Pavement			
a)	Road Junction			S/U V
b)	Condition of Surfacing			S/U ✓
c)	Riding Quality			S/U ✓
d)	Road Camber			S/U
e)	Whether free	from defects such a se of CC Pavement.	s visible cracks, exposed	Yes/Noral
f)	-	ts provided or not (CC)	Pavement) N.A.	Yes/No
g)		lank/slope & raincuts if	any	Yes/No
2.	Cross Drainage	X-23		J.A.
			ulverts including its painting	S/SRI/U
a)	Condition of Abi	itment & Wing walls, S	lab in RCC culverts	S/SRI/U
)		ngs/słab/approach for I		S/SRI/U
-	AND AND ASSESSMENT OF THE PARTY	The state of the s		
	Road Furniture			/
5	Whether sign bostones/Pavement	oards/informatory/cauti coad markings are prov		entre di di
0	Compliance Hist	ory		1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1
	tatus of ATR's &			
1	Water Commencer			

Overall Rating

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	U

(Signature)

NAME: