

FIELD INSPECTION REPORT

Date of Inspection : 02/12/2020	District: muzaffarpur
Division : muzaffarpur East-2	Length (km): 2.55 km
Name of the Road: Hathnani PWD road to Bhagwanpur Gochha.	
Scheme/Programme:	MAINTENANCE (MR 3054)
Package No.:	Road Id No.:
Status of the Project:	Ongoing/Completed/Under Maintenance
Work is a case of:	New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No NA
f)	Contraction Joints provided or not (CC Pavement)	Yes/No NA
g)	Compaction of flank/slope & raincuts if any	Yes/No Flank Damage by PHED NW Jul 4/2021.
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U NA
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U NA
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	NA
a)	Status of ATR's & any others	NA

Overall Rating :

Satisfactory (S)	(S)
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Ganesh kumar
02/12/2020
(Signature)

NAME: GANESH KUMAR

DESIGNATION: JUNIOR ENGINEER