

# FIELD INSPECTION REPORT

Date of Inspection :		District: <u>Muzaffarpur</u>
Division : <u>Muzaffarpur East 2</u>		Length (km): <u>2.20 km</u>
Name of the Road: <u>MIR Tengsaha to Madhopur</u>		
Scheme/Programme:	MAINTENANCE ✓ <u>MR (3054)</u>	
Package No.:	Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance.	
Work is a case of:	New Connectivity/Up gradation/ Maintenance	
Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓ S/U
b)	Condition of Surfacing	✓ S/U
c)	Riding Quality	✓ S/U
d)	Road Camber	✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No -
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	✓ S/SRI/U
c)	Condition of railings/slab/approach for Bridges	✓ S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓ Yes/No
4.	Compliance History	
a)	Status of ATR's & others	

Overall Rating :

Some portion of the road damage in flood 2020

Satisfactory (S)	"S"
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NAME: - Baidyanath chandhary

DESIGNATION: - Junior Engineer

(Signature)