

FIELD INSPECTION REPORT

Date of Inspection:	02-12-2020	District:	SAMSTIPUR
Division:	RWD ROSERA	Length (km):	2.3km
Name of the Road:	Shivrajpur Thana more to Patwara Road	Scheme/Programme:	MAINTENANCE - MR-3054
Package No.:		Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance	Work is a case of:	New Connectivity/Upgradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	Not applicable
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	No

Overall Rating :

Satisfactory (S)	15'
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

[Signature]
02/12/20
R.C.

[Signature]
02/12/20
AG

(Signature)

NAME:

DESIGNATION: