

FIELD INSPECTION REPORT

Date of Inspection : 02.12.2020	District: Gaya.
Division : Gaya.	Length (km): 1.40 km.
Name of the Road: Gaya Panchayat road to Bhadar.	
Scheme/Programme: MAINTENANCE	3054 (old)
Package No.: -	Road Id No.:
Status of the Project:	Ongoing/Completed/Under Maintenance <i>Under maintenance</i>
Work is a case of:	New Connectivity/Up gradation/ Maintenance <i>maintenance.</i>

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓S/U
b)	Condition of Surfacing	✓S/U
c)	Riding Quality	✓S/U
d)	Road Camber	✓S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓Yes/No
f)	Contraction Joints provided or not (CC Pavement)	N/A. Yes/No
g)	Compaction of flank/slope & raincuts if any	✓Yes/No
2.	Cross Drainage	N/A.
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	NO

Overall Rating :

Satisfactory (S)	S.
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Harishankar

NAME:

Harishankar
2.12.20
(Signature) J.E.