FIELD INSPECTION REPORT

Date of I	nspection:		District: Muzafferbur		
Division: Musafferfur East 2		Length (km): 5-280 km			
Name of	the Rond: Bange				
Scheme/		ENANCE	MR(3054)		
Package			Road Id No.:		
			Under Maintenance		
Work is			p gradation/ Maintenance		
Sl. No.	Parameters to be checked			Remarks	
1.	Pavement		A A A A A A A A A A A A A A A A A A A		
a)	Road Junction condition			S/U	
b)	Condition of Surfacing			S/U	
c)	Riding Quality			S/U ·	
d)	Road Camber			\$/U	
c)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes No IN	
f)	Contraction Joints provided or not (CC Pavement)			Yes.No H	
g)	Compaction of tlank/slope & raincuts if any			Yes/No	
2.	Cross Drainage				
a)	Condition of head walls in Hume pipe culverts including its painting			s/sri/u	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			s/sri/u	
c)	Condition of railings/slab/approach for Bridges			S/SRI/U	
3.	Road Furniture				
a)	Whether sign boards/informatory/eautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No	
4.	Compliance History				
a)	Status of ATR's & any others			MO ATIL	

Overall Rating

Satisfactory (S)	"s"
Satisfactory but requires Improvement (SRI)	į į
Unsatisfactory (U)	7

(Signal Jel) 20

NAME: Bandyarath chandharry

DESIGNATION: Sunter Engiteer

Scanned with CamScanner