

FIELD INSPECTION REPORT

Date of Inspection : 02.12.2020 District: SAHARSA
 Division : SIMRI BAKHTIYARPUR Length (km): 3.190
 Name of the Road: KHDJU CHACK TO CHAPRAM
 Scheme/Programme: MAINTENANCE ✓
 Package No.: Road Id No.: 20904400805
 Status of the Project: Ongoing/Completed Under Maintenance ✓
 Work is a case of: New Connectivity/Up gradation/ Maintenance ✓

No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/✓
b)	Condition of Surfacing	S/✓
c)	Riding Quality	S/✓
d)	Road Camber	S/✓
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement. N.A.	Yes/No
f)	Contraction Joints provided or not (CC Pavement) N.A.	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No ✓
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/✓
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/✓
c)	Condition of railings/slab/approach for Bridges	S/SRI/✓
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/lan & 200m stones/Pavement road markings are provided and maintained	Yes/No ✓
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

1/12/2020
 (Signature)

NAME:

KHOLIQUEZZAMAN
 SUPERINTENDING ENGINEER