FIELD INSPECTION REPORT

Date of Inspection :	2.12.20	District: PATHA	
Division: N	cseurhi	Length (km): 3.45	
		head to Kangara via Garhang	
Scheme/Programme:	MAINTENANCE	OLA	
Package No.:		Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

SL No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	√S/U
b)	Condition of Surfacing	√s/u
c)	Riding Quality	√s/u
d)	Road Camber	✓ s/u
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	√Yes/No
, jet	Close Dividinge - will	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	✓S/SRI/U
	Cond Christian	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	
Y 3 44 3		
a)	Status of ATR's & any others	MO

Overall Rating

Satisfactory (S)	(2)
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

AAW 211~ (Signature)

NAME: Ajay Kumar Lingh DESIGNATION: Executive Engineer