

FIELD INSPECTION REPORT

Date of Inspection : 2.12.2020		District : GAYA
Division : Neemchak Bathani		Length (Km. : 2.4 Km
Scheme/Programme: MR-3054		MAINTENANCE
Package No. : Name of Rd :- Gaya - Nwada Rd to Gandhi		Road Id No. :
Status of the Project :		Ongoing/Completed/Under Maintenance
Work is a case of :		New Connectivity/Up gradation/Maintenance
Sl. No.	Parameters to be checked	Remarks
1	Pavement	
a)	Road Junction condition	✓ S/U
b)	Condition of Surfacing	✓ S/U
c)	Riding Quality	✓ S/U
d)	Road Camber	✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No ✓
f)	Contraction Joints provided or not (CC Pavement)	✓ Yes/No
g)	Compaction of flank/slope & raincuts if any	✓ Yes/No
2	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	✓ S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	✓ S/SRI/U
c)	Condition of railings/slab/approach for Bridges	✓ S/SRI/U
3	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓ Yes/No
4	Compliance History	
a)	Status of ATR's & any others. ATR-NO-6051, awarded Grade-RI has not been removed yet	

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	—
Unsatisfactory (U)	—

2.12.2020
J.E