

FIELD INSPECTION REPORT

Date of Inspection :	02-12-2020	District:	PURNEA
Division :	PURNEA	Length (km):	1.645
Name of the Road:	REPAIR OF ROAD FROM KAMALPUR MIDDLE SCHOOL to beyond more Santhali' tola.		
Scheme/Programme:	MAINTENANCE		
Package No.:		Road Id No.:	21105200837
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	-
Satisfactory but requires Improvement (SRI)	-
Unsatisfactory (U)	✓ (U)

NAME:

SANJAY KUMAR SINHA

S.E. PURNEA

(Signature) 2/11/20

(SANJAY KR. SINHA)