

# FIELD INSPECTION REPORT

Date of Inspection: 02-12-2020 District: Nalanda  
 Division: Hilsa Length (km): 3.35 km  
 Name of the Road: Gopaspur to Nalanda - Amar  
 Scheme/Programme: MAINTENANCE Maintenance  
 Package No.: Road Id No.:  
 Status of the Project: Ongoing/Completed/Under Maintenance Under maintenance  
 Work is a case of: New Connectivity/Up gradation/ Maintenance Upgradation  
 Work is a case of: Re-works

| Sl. No. | Parameters to be checked                                                                                               | Remarks      |
|---------|------------------------------------------------------------------------------------------------------------------------|--------------|
| 1.      | Pavement                                                                                                               | -S           |
|         | Overall surface condition                                                                                              | -S           |
|         | Condition of Surfacing                                                                                                 | -S           |
| 2.      | Riding Quality                                                                                                         | -S           |
| d)      | Road Camber                                                                                                            | -S           |
| e)      | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.                           | -Yes         |
| f)      | Contraction Joints provided or not (CC Pavement)                                                                       | -Yes         |
| g)      | Compaction of flankslope & raincuts if any                                                                             | Yes/No - Yes |
| 3.      | Cross Drainage                                                                                                         | -S           |
| i)      | Condition of Road walls in Home pipe culverts including drainage                                                       | -S           |
| j)      | Condition of Abutment & Wing walls, Slab in RCC culverts                                                               | -S           |
| k)      | Condition of approach for Bridges                                                                                      | -S           |
| 4.      | Road Furniture                                                                                                         | -S           |
|         | Whether sign boards/informatory/cautionary Board/line & markings on pavement road markings are provided and maintained | -Yes         |
| 5.      | Compliance History                                                                                                     | -S           |
| 6)      | Status of A/R & any others                                                                                             | -S           |

Overall Rating

Satisfactory (S)

Satisfactory but requires improvement (SR)

Unsatisfactory (U)

Satisfactory

NAME: Pradeep Kumar Arora

21/12/20  
J. Arora