FIELD INSPECTION REPORT

Date	of Inspection: 2.12.20 District: Buxan		
DIVIS	non: Onyear Length (km): 1."		
Sahar	cofthe Road: Prora Dlanoi road to syalker you		
	me/Programme: MAINTENANCE		
Status	age No.: MR-M 12 - 20-10-per/08 Road Id No.: s of the Project: Ongoing/Completed/Under Maintenance		
Work	ork is a case of: Ongoing/Completed/Under Maintenance New Connectivity/Up gradation/ Mgintenance		
SI. No	-1.1 - 1.2 III III III III III III III III III I	Remarks	
	The state of the s		
`.Y	Pavement		
a)	Road Junction condition		
b)	Condition of Surfacing		
c)	Riding Quality		
d)	Road Camber		
c)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		
ŋ	Contraction Joints provided or not (CC Pavement) (N/A)		
g)	Compaction of flank/slope & raincuts if any		
2	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting		
b)	Condition of Abutment & Wing walls, Slab in RCC culverts		
c)	Condition of railings/slab/approach for Bridges	A/A S/SRI/U	
3.	Road Furniture		
n) :	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained		
應	Compliance History		
1)	Status of ATR's & any others	No	

Overall Rating

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	-

NAME:

N.K. Himan

DESIGNATION:

सहायक अभियंता ग्रामीण कार्य विभाग कार्य अवर प्रमंडल, राजपुर

2.12.20 (Signature)

सहायक अभियंता ग्रामीण कायं विभाग कार्य अवर प्रमंडल, राजपुर

Scanned with CamScanner