FIELD INSPECTION REPORT

ame of	the Road: Fa	etemplar Ragi	auli road to Bha	Yer	
heme/	Programme:	MAINTENANCE	Hen Maintenance	8	54 Cy - 20
ickage	No.: MR-H/1	9-20/Gaya (09.	Road Id No.:	programme and the second	part of part of the same of th
tatus of the Project: Ongoing/Complete		Ongoing/Complete		Completed	
ork is	a case of:	1	/Up gradation/ Maintenance	Mae	
I. No.		Parameters	to be checked		Remarks
1.	Pavement				and the state of t
a)	Road Junction	n condition			\STU
b)	Condition of Surfacing				VS/U
c)	Riding Quality			(18) (10) (10) (10) (10) (10) (10) (10) (10	√S/U
management of the same of the	Road Camber			especial established de de	\S/U
d) e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			osed	Yes/No
f)	Contraction Joints provided or not (CC Pavement)			and the same of th	Yes/No
g)	Compaction of flank/slope & raincuts if any				"Yes/No
2.	Cross Drain				
a)	Condition of head walls in Hume pipe culverts including its painting				√8/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts				S/SRI/U
c)	Condition of railings/slab/approach for Bridges			S/SRI/U	
3.	Road Furni	200000000000000000000000000000000000000			
a)		n boards/informate	ory/cautionary Board/km & are provided and maintained	200m	Yes/No
4.	Compliance	History			8.34
a)	Status of ATR's & any others			nga pagawan kapatakan kapin adal masan masa	110
-)					Standing of the Control of
Overall Rating :		Satisfactory (S)		\$.
		Satisfactory b	out requires Improvement (\$	RI)	
		Unsatisfactor			

(Signature)

3.E

NAME: Ghanshyan Rathak Pankoj