

FIELD INSPECTION REPORT

Date of Inspection : 02.12.2020	District: Gaya.
Division : Gaya.	Length (km): 1.00 km
Name of the Road: Tankuppa Aadarakhi chak to Mankodika.	
Scheme/Programme:	MAINTENANCE New Maintenance Policy 2018
Package No.: MR-N/19-20/Gaya-07.	Road Id No.:
Status of the Project:	Ongoing/Completed/Under Maintenance Completed.
Work is a case of:	New Connectivity/Up gradation/ Maintenance Maintenance.

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓ S/U
b)	Condition of Surfacing	✓ S/U
c)	Riding Quality	✓ S/U
d)	Road Camber	✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No N/A
f)	Contraction Joints provided or not (CC Pavement)	Yes/No N/A
g)	Compaction of flank/slope & raincuts if any	✓ Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	✓ S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U N/A
c)	Condition of railings/slab/approach for Bridges	S/SRI/U N/A
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & stones/Pavement road markings are provided and maintained	200m ✓ Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	NO

Overall Rating :

Satisfactory (S)	S.
Satisfactory but requires Improvement (SRI)	—
Unsatisfactory (U)	—

NAME: Ghanshyam Rathak Tankup

(Signature)

02.12.2020
EE.