

FIELD INSPECTION REPORT

Date of Inspection : 02.12.2020	District: Gaya
Division : Gaya	Length (km): 1.30 km
Name of the Road: Bhaseria road to Bara Gram	
Scheme/Programme: MAINTENANCE	New maintenance Policy 2018.
Package No.: MR-N/19-20/Gaya-10	Road Id No.:
Status of the Project: Ongoing/Completed/Under Maintenance	ongoing.
Work is a case of: New Connectivity/Up gradation/ Maintenance	Maintenance.

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓ S/U
b)	Condition of Surfacing	✓ S/U
c)	Riding Quality	✓ S/U
d)	Road Camber	✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No N/A
f)	Contraction Joints provided or not (CC Pavement)	Yes/No N/A
g)	Compaction of flank/slope & raincuts if any	Yes/No ✓
2.	Cross Drainage yet Not Started.	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & stones/Pavement road markings are provided and maintained	200m Yes/No ✓
4.	Compliance History	
a)	Status of ATR's & any others	NO.

Overall Rating :

Satisfactory (S)	—
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	—

02/12/2020
(Signature) E.E.

NAME: Ghanshyam Pathak Pankaj