


## FIELD INSPECTION REPORT

<b>Date of Inspection :</b> 02.12.20	<b>District:</b> Gaya
<b>Division :</b> Gaya	<b>Length (km):</b> 4.90
<b>Name of the Road:</b> Nawadaha to Patkappa.	
<b>Scheme/Programme:</b>	MAINTENANCE
<b>Package No.:</b>	<b>Road Id No.:</b>
<b>Status of the Project:</b>	Ongoing/Completed/Under Maintenance
<b>Work is a case of:</b>	New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement <i>Not started.</i>	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage <i>Not started.</i>	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & stones/Pavement road markings are provided and maintained	200m Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	-
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	-

  
 (Signature)

NAME: *Ghanashyam Bhatnagar*