

FIELD INSPECTION REPORT

Date of Inspection : 2-12-20		District : GAYA	
Division : Nirmal Bahani		Length (Km) : 3.75 Km	
Scheme/Programme :		Road Id No. :	
Package No. : Repair of road from		MAINTENANCE	
Status of the Project : Road Id. No. 1		Ongoing/Completed/Under Maintenance	
Work is a case of :		New Connectivity/Up gradation/Maintenance	
SL No.	Parameters to be checked		Remarks
1	Pavement		
a)	Road Junction condition		✓SU
b)	Condition of Surfacing		✓SU
c)	Riding Quality		✓SU
d)	Road Camber		✓SU
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		✓SU
f)	Contraction Joints provided or not (CC Pavement)		✓SU
g)	Compaction of flank/slope & raincuts if any		✓Yes/No
2	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting		✓Yes/No
b)	Condition of Abutment & Wing walls, Slab in RCC culverts		✓Yes/No
c)	Condition of railings/slab/approach for Bridges		SRI
3	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided		S/SRI/U
4	Compliance History		
a)	Status of ATR's & any others.		S/SRI/U

Overall Rating :

Satisfactory (S) ✓	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Lalendra Singh
2.12.20
S-E