

FIELD INSPECTION REPORT

Date of Inspection :	02/12/2020	District:	Mauwada
Division :	Mauwada	Length (km):	4.810 KM
Name of the Road:	BARAUMA - GRAINI		
Scheme/Programme:	MAINTENANCE (3054)		
Package No.:	MR (3054)	Road Id No.:	10502602028
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓S/U
b)	Condition of Surfacing	✓S/U
c)	Riding Quality	✓S/U
d)	Road Camber	✓S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No M.O
f)	Contraction Joints provided or not (CC Pavement)	Yes/No M.O
g)	Compaction of flank/slope & raincuts if any	✓Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	✓S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & stones/Pavement road markings are provided and maintained	200m ✓Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	M.O

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	—
Unsatisfactory (U)	—

NAME:

Amash
2/12/2020
J.E. Mauwada

(Signature) 2/12/2020
A.E. Mauwada