

FIELD INSPECTION REPORT

(5)

Date of Inspection : 02/12/2020		District: Nawada
Division : Rajauli		Length (km): 1.80 K.M.
Name of the Road: Pachampha to Ginni Chahel		
Scheme/Programme: MAINTENANCE		
Package No.: MR-N/19-20 Rajauli - II		Road Id No.:
Status of the Project: Ongoing/Completed/Under Maintenance		
Work is a case of: New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No No. C.C. Pavement
f)	Contraction Joints provided or not (CC Pavement)	Yes/No N/A
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U N/A
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	N/A

Overall Rating :

Satisfactory (S)	—
Satisfactory but requires Improvement (SRI)	S
Unsatisfactory (U)	—


 2/12/20
 (Signature)

NAME: Manoj Kumar

DESIGNATION: E.E.R.W.D. Rajauli