

FIELD INSPECTION REPORT

Date of Inspection : 2/12/20 District: Arrangabad
 Division : Arrangabad Length (km): 2.10 km
 Name of the Road: Lurtha Sakerabad Rd to Sikariyane Nigampur
 Scheme/Programme: MAINTENANCE
 Package No.:
 Status of the Project: Ongoing ☒ Completed ☐ Under Maintenance ☐
 Work is a case of: New Connectivity/Up gradation: Maintenance ☒

Sl. No.	Parameters to be checked		Remarks
1.	Pavement		
a)	Road Junction condition		
b)	Condition of Surfacing	S	S/U
c)	Riding Quality	S	S/U
d)	Road Camber	S	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	S	S/U
f)	Contraction Joints provided or not (CC Pavement)	N/D	Yes/No
g)	Compaction of flank/slope & raincuts if any	Y	Yes/No
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	N/A	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	N/A	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	N/A	S/SRI/U
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Y	Yes/No
4.	Compliance History		
a)	Status of ATR's & any others		

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NAME: SE, Arrangabad

(Signature)