

FIELD INSPECTION REPORT

DATE OF INSPECTION:	02/12/2020	DISTRICT: PURNAEA
DIVISION:	DHAMDAHA	
NAME OF THE ROAD:	Sarsi Road (near Abiram) milli sonda via Kadarganj	
SCHEME/PROGRAMME:	MAINTENANCE MR-3054-HED	
PACKAGE No:	ROAD ID No.: HED 22000 1842	
STATUS OF THE PROJECT:	ONGOING/COMPLETED/UNDER MAINTENANCE	
WORK IS A CASE OF:	NEW CONNECTIVITY/UP GRADATION/MAINTENANCE	
SL.NO	PARAMETERS TO BE CHECKED	REMARKS
1	PAVEMENT	
A	ROAD JUNCTION CONDITION	S
B	CONDITION FO SURFACING	S
C	RIDING QUALITY	S
D	ROAD CAMBER	S
E	WHETHER FREE FROM DEFECTS SUCH AS VISIBLE CRACKS, EXPOSED AGGREGATES IN CASE FO CC PAVEMENT	Yes
F	CONTRACTION JOINTS PROVIDED OR NOT(CC PAVEMENT)	H/A
G	COMPACTION OF FLANK/SLOPE & RAINCUTS IF ANY	Yes
2	CROSS DRAINAGE	
A	CONDITION OF HEAD WALLS IN HUME PIPE CULVERTS INCLUDING ITS PAINTING	S
B	CONDITION OF ABUTMENT & WING WALLS, SLAB IN RCC CULVERTS	S
C	CONDITION OF RAILINGS/SLAB /APPROACH FOR BRIDGES	S
3	ROAD FURNITURE	
A	WHETHER SIGN BOARDS /INFORMATORY BOARD/ KM & 200 M STONES/PAVEMENT ROAD NARKING ARE PROVIDED AND MAINTAINED	Yes
4	COMPLIANCE HISTORY	
A	STATUS OF ATR's & ANY OTHERS	No Any ATR
OVERALL RATING	SATISFACTORY(S)	S
	SATISFACTORY BUT REQUIRES IMPROVEMENT(SRI)	-
	UNSATISFACTORY(U)	-

NAME: Arjun Kumar Singh
 DESIGNATION: E.E. ROD (O.D) Dhamdaha

Signature
 02-12-20
 E.E.ROD (O.D) Dhamdaha