

FIELD INSPECTION REPORT

Date of Inspection: 02.12.2020	District: Vaishali
Division: Hasibpur	Length (km): 1.582
Name of the Road: Hazaro Hanuman Mandir to Kushwaha Tola	
Scheme Programme: MAINTENANCE	
Package No.:	Road Id No.:
Status of the Project: Ongoing/Completed/Under Maintenance	
Work is a case of: New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	SU
b)	Condition of Surfacing	SU
c)	Riding Quality	SU
d)	Road Camber	SU
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRLU
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRLU
c)	Condition of railings/slab/approach for Bridges	S/SRLU
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	☒
Satisfactory but requires Improvement (SRI)	☐
Unsatisfactory (U)	☐

NAME:

DESIGNATION:

Gay
21/2/20

E.E

R.W.D

works div.

Hasibpur

(Signature)
2-12-20