

# **FIELD INSPECTION REPORT**

|                                                               |                      |
|---------------------------------------------------------------|----------------------|
| Date of Inspection: 02.12.2020                                | District: - Vaishali |
| Division: - Hazibpur                                          | Length (km): - 3.30  |
| Name of the Road: Primary School Chak Jaziya to Pishumbur.    |                      |
| Scheme Programme: MAINTENANCE                                 | 3054-MR              |
| Package No.:                                                  | Road Id No.:         |
| Status of the Project: Ongoing/Completed/Under Maintenance    |                      |
| Work is a case of: New Connectivity/Up gradation/ Maintenance |                      |

| Sl. No. | Parameters to be checked                                                                                             | Remarks |
|---------|----------------------------------------------------------------------------------------------------------------------|---------|
| 1.      | Pavement                                                                                                             | ✓       |
| a)      | Road Junction condition                                                                                              | SU      |
| b)      | Condition of Surfacing                                                                                               | ✓ SU    |
| c)      | Grading Quality                                                                                                      | ✓ SU    |
| d)      | Road Camber                                                                                                          | ✓ S.U.  |
| e)      | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.                         | ✓ N/A   |
| f)      | Contraction Joints provided or not (CC Pavement)                                                                     | ✓ N/A   |
| g)      | Compaction of flank slope & raincurbs if any                                                                         | ✓ S.U.  |
| 2.      | Cross Drainage                                                                                                       |         |
| a)      | Condition of head walls in Hume pipe culverts including its painting                                                 | ✓ SRIU  |
| b)      | Condition of Abutment & Wing walls, Slab in RCC culverts                                                             | ✓ SRIU  |
| c)      | Condition of railings/slab approach for Bridges                                                                      | ✓ SRIU  |
| 3.      | Road Furniture                                                                                                       |         |
| a)      | Whether sign board/informatory/cautionary Board km & 200m stretch Pavement road markings are provided and maintained | ✓ S.U.  |
| 4.      | Compliance History                                                                                                   |         |
| a)      | Status of ATR's & any others                                                                                         | N/A     |

Overall Rating

|                                             |   |
|---------------------------------------------|---|
| Satisfactory (S)                            | ✓ |
| Satisfactory but requires Improvement (SRI) |   |
| Unsatisfactory (U)                          |   |

NAME:

DESIGNATION:

9/12/20  
B. B.  
R.D.  
HAZIBPUR

(Signature)