


FIELD INSPECTION REPORT

Date of Inspection :	02.12.2020	District:	East Champaran.
Division :	Raxaul	Length (km):	5. KM.
Name of the Road:	NH-28 to ^{Padma} Bandhiyadi Ghat - PART-3		
Scheme/Programme:	MAINTENANCE New Maintenance Policy 2018		
Package No.:	3	Road Id No.:	NEA 22000314
Status of the Project:	☒ Ongoing/ ☒ Completed/ ☐ Under Maintenance		
Work is a case of:	☒ New Connectivity/ ☐ Up gradation/ ☐ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓ S/U
b)	Condition of Surfacing	✓ S/U
c)	Riding Quality	✓ S/U
d)	Road Camber	✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No N/A
f)	Contraction Joints provided or not (CC Pavement)	Yes/No N/A
g)	Compaction of flank/slope & raincuts if any	Yes/No N/A
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U N/A
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U N/A
c)	Condition of railings/slab/approach for Bridges	S/SRI/U N/A
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No ✓
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	


(Signature)

NAME: Darshangee Devi

DESIGNATION: Executive Engineer.
R.W.D. Raxaul.