## FIELD INSPECTION REPORT

Date of Inspection: 3/12/2000 District: Patra.				
Division: Patra, Length (km): 2.50 KM				
Name of the Road: Chiotya to Gylhariya tak				
Scheme/Programme: MAINTENANCE				
Package No.: MR-N-2019-20/am 08 Road Id No.:  Status of the Project: Ongoing/Completed/Under Maintenance (NEW Maintenance)				
Status of	amona	104 9 2019		
Work is a case of: New Connectivity/Up gradation/ Maintenance				1
Sl. No.	Parameters to be checked Remarks			
1:	Pavement			
a)	Road Junction	condition	S/U	
b)	Condition of S	Surfacing	S/U	
c)	Riding Quality	7	S/U	
d)	Road Camber	ą,	S/U	
e)		from defects such as visible cracks, exposed case of CC Pavement.	Yes/No	
f)	Contraction Jo	pints provided or not (CC Pavement)	Yes/No	
g)	Compaction of	f flank/slope & raincuts if any	Yes/No	
2.	Cross Drainage — N.A			
a)	Condition of h	ead walls in Hume pipe culverts including its painting	S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts		S/SRI/U	1
c)	Condition of railings/slab/approach for Bridges		S/SRI/U	-
3.	Road Furnitu	re .		
a)	Whether sign stones/Paveme	boards/informatory/cautionary Board/km & 200m ent road markings are provided and maintained	Yes/No	
4.	Compliance I	listory — NO		
a)	Status of ATR	's & any others	A Line William Zer	

Overall Rating

•	
Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	
	1 1

NAME: Maheshum Pannyh DESIGNATION: JE (Signature)

Scanned with CamScanner