FIELD INSPECTION REPORT

Date of Inspection :	3/12/2000	District:	Palma.		
Division: Pama.		Length (km): 2 · 40 / 57			
Name of the Road: N	Tola.				
Scheme/Programme:					
Package No.: MR-N-					
Status of the Project:	Ongoing/Completed/Under Maintenance (New Maintenance Pol				
Work is a case of:	New Connectivity/Up gradation/ Maintenance				7

Sl. No.	Parameters to be checked	Remarks
11:	Payement	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage — N.A	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	77.0
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History — ND (CATALON ASSESSED
a)	Status of ATR's & any others	20 117 dig 2

Overall Rating

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NAME: Maheshwir Pannyo DESIGNATION: JE (Signature)3)12/2000