FIELD INSPECTION REPORT

Date of I	nspection: 02	. 12.2020 Di	strict:	atra		,
Division	: Danapus	Le	ength (km):	2.561		
Name of	the Road:	ghurampus pancho ndasbus Muchari	Har and h	chismichal to	Dhaneses s	ing
Scheme/	Programme:	MAINTENANCE		77.7 1. 70		hou
			oad Id No.:			
Status of the Project: Orgoing/Completed/Under Maintenance Work is a case of: New Connectivity/Up gradation/ Maintenance						* 3
45	a case of:	New Connectivity/Up gr		intenance	LW. Torre Description of Colo	
SI. No.		Parameters to be c	checked		Remarks	
Ů	Pavement					
a)	Road Junction condition				S/U	
b)	Condition of Surfacing				S/U	
c)	Riding Quality				S/U	1
d)	Road Camber				S/U	1
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.				Yes/No	1
f)	Contraction Joints provided or not (CC Pavement)				Yes/No	
g)	Compaction of flank/slope & raincuts if any			Yes/No	\parallel	
2.	Cross Drainage					Zastaninia Tantaninia
a)	Condition of head walls in Hume pipe culverts including its painting				S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts				S/SRI/U	11
c)	Condition of railings/slab/approach for Bridges				S/SRI/U	1
3,	Road Furniture					1
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No		
4	Gompliance History					
a) ,	Status of ATR's & any others				(1) (1) (1) (1) (1) (1) (1) (1) (1) (1)	
Overall Rating: Work Started just mon.						1
O votati Natilig		Satisfactory (S)		S	12.	
		Satisfactory but requi	ires Improv	ement (SRI)	e Ar Tenes	
		Unsatisfactory (U)	4.		- 1 1 1	

NAME: chatulbhuj Mandal DESIGNATION: J.E.

Scanned with CamScanner

(Signature)