FIELD INSPECTION REPORT

Date of 1	nspection: 6	2.12.2020	District: patua	1.75
Division: Danabuz Length (km): 1.821				. 1.4
Name of the Road: Danapur Contonment to chandmere todipus				
Scheme/Programme: MAINTENANCE				
Package No.: MR-N 19-20-Daugus 03 Road Id No.:				
Status of the Project: Ongoing/Completed/U				
Work is a case of: New Connectivity/Up gradation/ Maintenance				
SI. No.		Parameters to	oe checked	Remarks
1	Payement			
a)	Road Junction condition			S/U
b)	Condition of Surfacing			S/U
c)	Riding Quality			S/U
d)	Road Camber			S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No
f)	Contraction Joints provided or not (CC Pavement)			Yes/No
g)	Compaction of flank/slope & raincuts if any			Yes/No
2.	Cross Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U
b) '	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U
c)	Condition of railings/slab/approach for Bridges			S/SRI/U
3.	Road Fürnifüre			
a)				Yes/Ne-
4.4	Compliance History			
a)	Status of ATR's & any others			
Overall Rating: Nork not started. Satisfactory (S)				

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

02/12/20 02/12/20

NAME: chatusbtuy Mandel

DESIGNATION: J-B'

(Signature)

Scanned with CamScanner

N/A